

Instruction Manual

PS-12 Inductive Proximity Sensor



CE

15 Columbia Drive Amherst, NH 03031 USA

Phone: (603) 883-3390 • Fax: (603) 886-3300 E-mail: <u>support@monarchinstrument.com</u> Website: www.monarchinstrument.com



SAFEGUARDS AND PRECAUTIONS



Read and follow all instructions in this manual carefully, and retain this manual for future reference.

Do not use this instrument in any manner inconsistent with these operating instructions or under any conditions that exceed the environmental specifications stated.

This instrument is not user serviceable. For technical assistance, contact the sales organization from which you purchased the product.



In order to comply with EU Directive 2012/19/EU on Waste Electrical and Electronic Equipment (WEEE): This product may contain material which could be hazardous to human health and the environment. DO NOT DISPOSE of this product as unsorted municipal waste. This product needs

to be RECYCLED in accordance with local regulations; contact your local authorities for more information. This product may be returnable to your distributor for recycling; contact the distributor for details.

Monarch Instrument's Limited Warranty applies. See www.monarchinstrument.com for details.

Warranty Registration and Extended Warranty Coverage information is available online at www.monarchinstrument.com.

TABLE OF CONTENTS:

1.0	DESCRIPTION	.1
2.0	OPERATING PRINCIPLE	.1
3.0	CONNECTION DETAIL	.2
4.0	SETTING OPERATING DISTANCE	. 2
5.0	SPECIFICATIONS	.3
9	5.1 Dimension Measurements	.3

1.0 DESCRIPTION


The PS-12 is a three-wire sensor that outputs an open collector PNP pulse. The sensor operates at a 0.15 inch [4 mm] gap with a 0.45 inch [12 mm] target and has a red LED on-target indicator. The sensor is housed in a threaded metal IP67 shell and supplied with an M12 nut and 6 ft. shielded cable with tinned wires.



2.0 OPERATING PRINCIPLE


Inductive proximity switches are used for non-contact detection of metallic objects. Their operating principle is based on a coil and oscillator that creates an electromagnetic field in the close surroundings of the sensing surface. The presence of a metallic object in the operating area causes a dampening of the oscillation amplitude. The rise or fall of such oscillation is identified by a threshold circuit that changes the output of the sensor. Current consumption of an inductive proximity switch decreases proportional to the metal object distance.

3.0 CONNECTION DETAIL



4.0 SETTING OPERATING DISTANCE

To ensure stable operation at environmental extremes, the sensing distance should be set to 80% of the rated distance. The detection distance is dependent upon the size and material of the target. The PS-12 is specified for an iron target. A stainless steel target will reduce the sensing distance to 50%. Brass, aluminum or copper targets will reduce the sensing distance to around 40%.




5.0 SPECIFICATIONS

Specifications*	PS-12 Inductive Proximity Sensor
Power Required	6 - 36 V dc @ 15 mA
Output Signal	Open Collector PNP - normally open (NO)
Sensing Distance	0.15 in. [4 mm] Target should be at least = sensor diameter
Sense Indicator	LED indicates target present
Maximum Speed	24,000 RPM (400 Hz)
Operating Temperature	-13° to +167 °F [-25° to +75 °C]
Cable Length	Including sensor, 6 ft. [1.8 m]
Material	Threaded metal
Housing Protection	IP67
Mechanical	Standard size: M12
Dimensions	2.36 in. x 0.48 in. diameter [60 mm x 12 mm]

^{*}Specifications are subject to change without notice.

5.1 Dimension Measurements

Measurements in mm.



This page is intentionally left blank.

The Professional's Choice

Monarch Instrument is committed to excellence and auality in manufacturing, sales, and service.



Tachometers



Track-It[™] Data Loggers



Panel Tachometers



Fixed Mounted Strobes



Portable Strobes



Frequency Converters









15 Columbia Drive, Amherst NH 03031 USA Tel.: (603) 883-3390 // Fax: (603) 886-3300 Email: support@monarchinstrument.com Website: www.monarchinstrument.com