TRH-554-WP

Temperature & Humidity Transmitter





Features

- Highly accurate Digital technology sensor gives fast and reliable output.
- Temperature range is -20 to 60°C with accuracy of ± 0.5 °C.
- Relative Humidity range is 0 to 100%RH with accuracy of ± 2 %RH.
- Long term stable output for both Temperature and Relative Humidity.
- Digital Display of Temperature & Relative Humidity on Seven Segment Display
- Standard 4-20mA signal outputs with configurable range.
- Easy handling & programming with 3 keys
- · Password protected programming with password changing facility.
- Software calibration for both Temperature & Relative Humidity.
- Flash memory for data security in the event of power failure
- Optional 2 nos. Alarm relay contacts with two configurable Alarm levels & one relay for fail safe relay.
- Optional Isolated RS-485 communication port with MODBUS RTU Protocol.
- Compact size, can be easily installed

Applications

- Clean Rooms
- Server Room
- Pharmaceutical
- Hospitals / Labs
- Walk-in-cooler
- Greenhouse Breeding
- Warehouse / Cold Room
- Indoor Air Quality (IAQ)
- Air Condition Room
- Energy Management System (EMS)

MUST FOR HUMAN & INDUSTRIAL SAFETY

TECHNICAL SPECIFICATIONS

Output Signal

Standard

General Sensor Type : Capacitive Polymer sensor Range : For Temperature :-20 to 60 °C For Relative Humidity: 0 to 100% RH Display : 2-Line, 4-Digit 13mm (H) Seven Segment Display. 8 LEDs to indicate status of instrument. Control Action : i) Two independent Alarm set points with Latch & Non-latch facility. : ii) User selectable Hysteresis Setting : By 3 Keys on front panel for WP model Performance Measurement : ± 0.5°C for Temperature Accuracy : ± 2% RH for Relative Humidity Response Time : Approx 5 Seconds Electrical Supply Voltage : 18 to 36 VDC; Typically 24VDC. Power Consumption : Less than 3.5 Watts Cable : 3 Wires (1.5 mm²) Flexible or Armoured Shielded Cable Error Monitoring • • During Sensor break / open, the Display shows '5En5 GPEn' & output currer will be as per Upscale/Downscale. • During Over Range the Display Shows '0VER' & Under range Display Shows					
Range : For Temperature :-20 to 60°C For Relative Humidity : 0 to 100% RH Display : 2-Line, 4-Digit 13mm (H) Seven Segment Display. 8 LEDs to indicate status of instrument. Control Action : i) Two independent Alarm set points with Latch & Non-latch facility. : ii) User selectable Hysteresis Setting : By 3 Keys on front panel for WP model Performance Measurement : ± 0.5°C for Temperature Accuracy : ± 2% RH for Relative Humidity Response Time : Approx 5 Seconds Electrical Supply Voltage Supply Voltage : 18 to 36 VDC; Typically 24VDC. Power Consumption : Less than 3.5 Watts Cable : 3 Wires (1.5 mm²) Flexible or Armoured Shielded Cable Error Monitoring • • During Sensor break / open, the Display shows '5E n 5 DPE n' & output currer will be as per Upscale/Downscale.	General				
For Relative Humidity : 0 to 100% RH Display : 2-Line, 4-Digit 13mm (H) Seven Segment Display. 8 LEDs to indicate status of instrument. Control Action : i) Two independent Alarm set points with Latch & Non-latch facility. : ii) User selectable Hysteresis Setting : By 3 Keys on front panel for WP model Performance Measurement : ± 0.5°C for Temperature Accuracy : ± 2% RH for Relative Humidity Response Time : Approx 5 Seconds Electrical Supply Voltage Supply Voltage : 18 to 36 VDC; Typically 24VDC. Power Consumption : Less than 3.5 Watts Cable : 3 Wires (1.5 mm ²) Flexible or Armoured Shielded Cable Error Monitoring • • During Sensor break / open, the Display shows 'SE n5 OPE n' & output currer will be as per Upscale/Downscale.	Sensor Type	: Capacitive Polymer sensor			
Display : 2-Line, 4-Digit 13mm (H) Seven Segment Display. 8 LEDs to indicate status of instrument. Control Action : i) Two independent Alarm set points with Latch & Non-latch facility. : ii) User selectable Hysteresis Setting : By 3 Keys on front panel for WP model Performance Measurement : ± 0.5°C for Temperature Accuracy : ± 2% RH for Relative Humidity Response Time : Approx 5 Seconds Electrical Supply Voltage : 18 to 36 VDC; Typically 24VDC. Power Consumption : Less than 3.5 Watts Cable : 3 Wires (1.5 mm²) Flexible or Armoured Shielded Cable Error Monitoring * • During Sensor break / open, the Display shows 'SEn5 OPEn' & output currer will be as per Upscale/Downscale.	Range	: For Temperature : -20 to 60°C			
8 LEDs to indicate status of instrument. Control Action : i) Two independent Alarm set points with Latch & Non-latch facility. : ii) User selectable Hysteresis Setting : By 3 Keys on front panel for WP model Performance Measurement : ± 0.5°C for Temperature Accuracy : ± 2% RH for Relative Humidity Response Time : Approx 5 Seconds Electrical Supply Voltage : 18 to 36 VDC; Typically 24VDC. Power Consumption : Less than 3.5 Watts Cable : 3 Wires (1.5 mm²) Flexible or Armoured Shielded Cable Error Monitoring • • During Sensor break / open, the Display shows '5E n 5 DPE n' & output currer will be as per Upscale/Downscale.		For Relative Humidity : 0 to 100% RH			
Control Action : i) Two independent Alarm set points with Latch & Non-latch facility. : ii) User selectable Hysteresis Setting : By 3 Keys on front panel for WP model Performance Measurement : ± 0.5°C for Temperature Accuracy : ± 2% RH for Relative Humidity Response Time : Approx 5 Seconds Electrical Supply Voltage : 18 to 36 VDC; Typically 24VDC. Power Consumption : Less than 3.5 Watts Cable : 3 Wires (1.5 mm²) Flexible or Armoured Shielded Cable Error Monitoring • • During Sensor break / open, the Display shows '5E n 5 DPE n' & output currer will be as per Upscale/Downscale.	Display	: 2-Line, 4-Digit 13mm (H) Seven Segment Display.			
& Non-latch facility. : ii) User selectable Hysteresis Setting : By 3 Keys on front panel for WP model Performance Measurement : ± 0.5°C for Temperature Accuracy : ± 2% RH for Relative Humidity Response Time : Approx 5 Seconds Electrical Supply Voltage : 18 to 36 VDC; Typically 24VDC. Power Consumption : Less than 3.5 Watts Cable : 3 Wires (1.5 mm²) Flexible or Armoured Shielded Cable Error Monitoring • • During Sensor break / open, the Display shows '5E n 5 DPE n' & output currer will be as per Upscale/Downscale.		8 LEDs to indicate status of instrument.			
Setting : By 3 Keys on front panel for WP model Performance Measurement : ± 0.5°C for Temperature Accuracy : ± 2% RH for Relative Humidity Response Time : Approx 5 Seconds Electrical Supply Voltage : 18 to 36 VDC; Typically 24VDC. Power Consumption : Less than 3.5 Watts Cable : 3 Wires (1.5 mm²) Flexible or Armoured Shielded Cable Error Monitoring • • During Sensor break / open, the Display shows '5E n 5 DPE n' & output currer will be as per Upscale/Downscale.	Control Action	,			
Performance Measurement : ± 0.5°C for Temperature Accuracy : ± 2% RH for Relative Humidity Response Time : Approx 5 Seconds Electrical Supply Voltage : 18 to 36 VDC; Typically 24VDC. Power Consumption : Less than 3.5 Watts Cable : 3 Wires (1.5 mm²) Flexible or Armoured Shielded Cable Error Monitoring • During Sensor break / open, the Display shows '5Em5 OPEm' & output currer will be as per Upscale/Downscale.		: ii) User selectable Hysteresis			
Measurement : ± 0.5°C for Temperature Accuracy : ± 2% RH for Relative Humidity Response Time : Approx 5 Seconds Electrical Supply Voltage : 18 to 36 VDC; Typically 24VDC. Power Consumption : Less than 3.5 Watts Cable : 3 Wires (1.5 mm²) Flexible or Armoured Shielded Cable Error Monitoring • • During Sensor break / open, the Display shows '5E n 5 DPE n' & output currer will be as per Upscale/Downscale.	Setting	: By 3 Keys on front panel for WP model			
Accuracy : ± 2% RH for Relative Humidity Response Time : Approx 5 Seconds Electrical Supply Voltage : 18 to 36 VDC; Typically 24VDC. Power Consumption : Less than 3.5 Watts Cable : 3 Wires (1.5 mm²) Flexible or Armoured Shielded Cable Error Monitoring • • During Sensor break / open, the Display shows '5En5 OPEn' & output currer will be as per Upscale/Downscale.	Performance				
Response Time : Approx 5 Seconds Electrical Supply Voltage : 18 to 36 VDC; Typically 24VDC. Power Consumption : Less than 3.5 Watts Cable : 3 Wires (1.5 mm²) Flexible or Armoured Shielded Cable Error Monitoring • During Sensor break / open, the Display shows '5Em5 OPEm' & output currer will be as per Upscale/Downscale.	Measurement	÷ ± 0.5°C for Temperature			
Electrical Supply Voltage : 18 to 36 VDC; Typically 24VDC. Power Consumption : Less than 3.5 Watts Cable : 3 Wires (1.5 mm²) Flexible or Armoured Shielded Cable Error Monitoring • During Sensor break / open, the Display shows '5E n 5 DPE n' & output currer will be as per Upscale/Downscale.	Accuracy	÷ ± 2% RH for Relative Humidity			
Supply Voltage : 18 to 36 VDC; Typically 24VDC. Power Consumption : Less than 3.5 Watts Cable : 3 Wires (1.5 mm²) Flexible or Armoured Shielded Cable Error Monitoring • • During Sensor break / open, the Display shows '5En5 OPEn' & output currer will be as per Upscale/Downscale.	Response Time	: Approx 5 Seconds			
Power Consumption : Less than 3.5 Watts Cable : 3 Wires (1.5 mm²) Flexible or Armoured Shielded Cable Error Monitoring • During Sensor break / open, the Display shows '5En5 DPEn' & output currer will be as per Upscale/Downscale.	Electrical				
Cable : 3 Wires (1.5 mm²) Flexible or Armoured Shielded Cable Error Monitoring • During Sensor break / open, the Display shows '5E n 5 DPE n' & output curre will be as per Upscale/Downscale.	Supply Voltage	: 18 to 36 VDC; Typically 24VDC.			
 Error Monitoring During Sensor break / open, the Display shows '5En5 OPEn' & output curre will be as per Upscale/Downscale. 	Power Consumption	Less than 3.5 Watts			
• During Sensor break / open, the Display shows '5E n 5 DPE n' & output curre will be as per Upscale/Downscale.	Cable	: 3 Wires (1.5 mm ²) Flexible or Armoured Shielded Cable			
will be as per Upscale/Downscale.	Error Monitorin	g			
	will be as per Ups	cale/Downscale.			

'UNDER' output current will be as per Upscale / Downscale

				Humidity Respectiv	vely	
	Optional			,	(one for failsafe and two for f rating "120VAC/2A, 24VDC/2A"	
	Optional		:	Isolated RS-485 Co RTU protocol.	ommunication port with MODBUS	
	Environmen	tal				
	Operating Tempera Humidity			-15 to +55°C Less than 95% Non	-Condensing.	
	Accessories					
	 C € certified 24 VDC Power supply. Canopy Mounting stand. SCADA Software. 			,	 RS-485 to USB convertor RS-232 to RS-485 convertor Hooter cum Flasher 	
	Weatherproof Housing					
ent	Protection Class Cabinet Material Cable Entry Dimension Mounting Weight	 IP-65 Polycarbonate, grey colour Thermoplastic cable gland (IP 68) 216 mm (H) x 103 mm (W) x 55 mm (D) (with 1 gland) 215 mm (H) x 125 mm (W) x 55 mm (D) (with 2 glands) Wall Mounting / Stand Mounting/Duct Mounting Approx 370 Grams. 				

WEATHERPROOF ENCLOSURE DIMENSIONS



Upscale current = 21mA Down scale current = 3.7mA

SIDE VIEW

BACK VIEW

: Two 4-20mA Current Outputs with configurable range

selection, one each for Temperature & Relative

